



Height Control Valve Repair Kits

1958 ~ 1981 GM and Ford Air Suspension

Models:

Buick—Riveria, Electra, Wildcat, Century, LeSabre,

Cadillac—Eldorado, Fleetwood, Seville, Calais

Chevrolet—Chevelle, Monte Carlo, Laguna, Truck

Pontiac—Tempest, Grand Prix, Le Man, GTO, Grand AM, Grand Safari



Oldsmobile—Cutlass, 440, F85, Vista Cruiser

Ford


Lincoln

More.....

The 'Original' Delco Height Control Valve

Delco designed two styles of Height Control Valves (HCV) starting in 1958.

The Non-Delay style HCV generally uses more air while driving. The air line connections are vertical. An alignment pin is required to center the valve for height adjustment. This style of valve is no longer available but we offer a Repair Kit to functionally repair the Valve. Note: The Kit does not include every part in the valve and some parts are visually different than the original.



Non-Delay HCV

The Delay style HCV is still in production today.

The delay style valve uses less air. The air line connections are horizontal and at the rear of the valve. It is simpler to adjust but must be mounted with the round cylinder on the valve, down. Kits are available with a new valve body but do not include the Mounting Bracket and Control Lever shown in this picture.



Delay HCV





K870007 HCV Repair Kit

\$48.90 ea.

Height Control Valve Assembly Kit, LH. This Kit is to rebuild a Delco **Delay Style Valve** and requires the use of parts from an original Valve. This Kit includes a new Left Hand mounting Valve Body Assembly and requires the use of the existing Mounting Bracket and Valve Control Arm. Some assembly is required; Kit instructions are included.

Part Numbers—3178891, 4939904, 4941232, 4950198, 4964304, 4974197, 4974267, 4974311, 4974363, 4974404, 4974405, 4992928, 4993977, 22007267, 22007268, 22007269, 22007647, 22007653

K870008 HCV Repair Kit

\$48.90 ea.

Height Control Valve Assembly Kit, RH. This Kit is to rebuild a Delco **Delay Style Valve** and requires the use of parts from an original Valve. This Kit includes a new Right Hand mounting Valve Body Assembly and requires the use of the existing Mounting Bracket and Valve Control Arm. Some assembly is required; Kit instructions are included.

Part Number—4974715



K050007 HCV Repair Kit

\$47.25 ea.

This Kit is to rebuild a Delco **Non-Delay Style Valve** and requires the use of parts from an original Valve. It includes: Gaskets, Seals, O-rings, Valve Cores, DOT Compression Fittings and parts typically necessary to rebuild a Valve that has had normal wear and tear, but no major damage to it. Kit instructions are included

Part Numbers—4939950, 4939951, 4941117, 4963761, 4992414, 4992415, 4992900, 4992901, 4992902, 5544816, 5544817, 5552939, 5554761, 5554762

P/N K050012 HCV Repair Kit

Price \$31.38 ea.

This Kit is to rebuild a Delco **Non-Delay Style Valve** and requires the use of parts from an original Valve. It includes: Gaskets, Seals, O-rings, Valve Cores and parts typically necessary to rebuild a Valve that has had normal wear and tear, but no major damage to it. Kit instructions are included. Same as K050007 above except DOT style Compression Fittings are not included.

Part Numbers—4939950, 4939951, 4941117, 4963761, 4992414, 4992415, 4992900, 4992901, 4992902, 5544816, 5544817, 5552939, 5554761, 5554762



Dayton Air Control Products 2785 Lance Drive Dayton, OH 45409 (800) 831-1893

www.levelingvalve.com

01/13